

SECRET

ILLEGIB

PRIORITY

IN 82673

TOR 2114Z 10 JUN 64

25X1A

TO PRIORITY

INFO

CITE 1823

OXCART

25X1A 25X1A

1. REF 1819 AND 8509

25X1A

2. [] WAS ADVISED AT EARLIEST DATE ON WHICH WE HAD A REASONABLY ACCURATE ASSESSMENT OF THE PROBLEM AND EXTENT. WE COULD HAVE ADVISED [] EARLIER, BUT EXTENT OF DAMAGE, TIME TO REPAIR, NECESSITY TO EXPEDITE VENDORS, AND PLAN OF ACTION WOULD ALL HAVE BEEN VAGUE HAD WE DONE SO. WE FELT IT WOULD CAUSE LESS CONFUSION TO CONCENTRATE ON ASSESSMENT UNTIL COMPLETE AND SUMMARIZE SITUATION TO YOU.

25X1A

3. WALL OUTLET RECENTLY INSTALLED CONTAINED ONE BLACK TERMINAL AT 6 O'CLOCK AND THREE REDS AT 3, 9, AND 12 O'CLOCK. BLACK TERMINAL WAS ASSUMED TO BE GROUND. AN ENGINEER CHECKED THE OUTLET FOR PHASING OF THE THREE RED TERMINALS AND IT WAS WRONGLY ASSUMED THAT THIS CHECK VERIFIED TOTAL CORRECTNESS OF WIRING INSTALLATION. SINCE PHASEMETER USED IN CHECK DOES NOT

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1A

1823 (IN 82678)

S E C R E T

PAGE TWO

INDICATE VOLTAGE MISWIRING OF BLACK TERMINAL AS A HOT
LEAD RATHER THAN GROUND WAS NOT DETECTED.

END OF MESSAGE

S E C R E T